

INFORMATION REPORT - INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

S-E-C-R-E-T

25X1

COUNTRY	East Germany	REPORT		25X1
SUBJECT	Soviet Tank Repair Shop, Wuensdorf: Work Data	DATE DISTR.	22 November 1955	25X1
		NO. OF PAGES	2	25X1
DATE OF INFO.		REQUIREMENT NO.	RD	25X1
PLACE ACQUIRED		REFERENCES		
DATE ACQUIRED		This is UNEVALUATED Information		25X1

SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

1. The following were observed to be stamped on T-34/85's and SU-100's undergoing repair in this depot between 1 and 13 August 1955:

25X1

Armored Vehicle

a. T-34/85

"
"
"
"
"
"
"
"
"
"
"
"
"
"

25X1

b.

25X1

S-E-C-R-E-T

25X1

STATE	ARMY	X	NAVY	X	AIR	X	FBI	AEC	ORR EV	X
-------	------	---	------	---	-----	---	-----	-----	--------	---

(Note: Washington distribution indicated by "X"; Field distribution by "#".)

25X1

INFORMATION REPORT - INFORMATION REPORT

S-E-C-R-E-T

25X1

25X1

-2-

(continued)

25X1

2. The August target figures for armored vehicle repairs were given as 29 T-34/85's and two T-34/76's without turret and gun which are to be used for training purposes. The turrets and guns of the latter were scrapped and a metal plate containing a hatch was placed over the turret ring.
3. The dismantling bays actually handled 33 T-34/85's and the two T-34/76's referred to above. However, four of the T-34/85's were, in fact, sent for scrap, being cut to pieces at the depot and sent off to an unknown destination by rail.

4. The following [redacted] were obtained during the period:

25X1

25X1

"T-34"

"
"
"
"
"
"
"
"

"SU-100"

5. On 27 August, 30 T-34/85's were waiting repair in the workshops yard.

25X1

S E C R E T

25X1